



781 East Washington Blvd., Los Angeles, CA 90021  
(213) 745-5312 FAX (213) 745-6372

## Certificate of Analysis

Page 1 of 1

Dos Cuadros Offshore Resources, L.L.C.  
290 Maple Court, Suite 290  
Ventura, CA 93003

File #:74146  
Report Date: 04/23/21  
Submitted: 04/16/21  
**PLS Report No.: 2104141**

Attn: Mr. Jay Rao Phone: (805) 535-2078 FAX:(805) 535-2075

**Project:** Edith Produced Water - Monthly

Sample ID: Produced Water (2104141-01) Sampled:04/15/21 06:00 Received:04/16/21 06:00										
Analyte	Results	Flag	D.F.	Units	PQL	Prep/Test Method	Prepared	Analyzed	By	Batch
Salinity as NaCl	22900		500	mg NaCl/l	500	EPA 300.0	EPA 300.0	04/22/21	04/23/21	cg BD12305

### Notes and Definitions

NA Not Applicable  
ND Analyte NOT DETECTED at or above the reported limit(s)  
NR Not Reported  
MDL Method Detection Limit  
PQL Practical Quantitation Limit

Authorized Signature(s)

Environmental Laboratory Accreditation Program Certificate No. 1131, Mobile Lab No. 2534, LACSD No. 10138

## CHAIN OF CUSTODY AND ANALYSIS REQUEST

DATE: 4-15-21

LAB NO. 2102414

COOLER TEMP: 70°

12/20

ANALYSIS REQUESTED

PROJECT NAME

## CONTAINER TYPES

A=Amber B=Brass G=Glass  
P=Plastic V=VOA Via! O=Other

Slide (1) shown

## Salinity

Remarks

Produced Water Temp: 142

[illegible]

### Turn Around time

24Hr.

48Hr

72Hr

5 day

standar

other